Discussion on “The Case Against Normal Plots of Effects”

Eric D. Schoen

Faculty of Applied Economics, University of Antwerp, Belgium
TNO, Zeist, Netherlands

Peter Goos

Faculty of Applied Economics and StatUa Center for Statistics, University of Antwerp, Belgium
Faculty of Bioscience Engineering and Leuven Statistics Research Centre (LSTAT), KU Leuven, Belgium

October 16, 2014

1 Introduction

Lenth pleads against the use of normal or half-normal plots of effects from two-level experiments to judge which effects may be active. Instead, he recommends utilizing Pareto charts of the effects supplemented with cutoff lines based on a robust estimator of the standard error.

Our discussion of Lenth’s paper consists of two parts. In the first part, we consider judging effects from full factorial or regular fractional factorial designs by normal or half-normal probability plots or robust estimators of the standard error. We recognize that the plots shown in Lenth’s paper are appealing, but we do not think that half-normal plotting should be entirely abandoned. In the second part of our discussion, we consider the case of nonregular designs or optimal designs, where robust standard errors and half-normal plotting of effects are of limited use and other methods of analysis need to be utilized.

2 Regular designs

2.1 Some history

Half-normal pots were introduced by Daniel (1959), who observed that absolute valued null effects ordered from small to large tend to be on a straight line through the origin when plotted on what he called ‘half-normal probability paper’. At that time, blocks of specially prepared sheets of *normal* probability paper could be purchased, where the vertical axis was used for the quantiles. By analogy, Daniel’s half-normal plots had the quantiles on the vertical axis and the effect sizes on the horizontal axis. As an example, Figure 1(a) shows the Daniel plot of effects based on the data of the regular 2^{5-1} fractional factorial design from Snee (1985), as reproduced in Lenth’s paper.

Daniel (1959) also observed that half-normal plots offer a way to detect one or two defective values, inadvertent plot-splitting or an antilognormal distribution of error. In this discussion, we restrict attention to the detection of a single defective value. For this purpose, we changed the 13th response value of Snee’s data from 5.22 to 2.22. Figure 1(b) shows the half-normal plot of effects based on the modified data. Because one response value is three units too small, the effects now are biased by either $-3/16$ or $3/16$, depending on the sign of the contrast corresponding to the defective value. Therefore, in absolute value, the null effects now no longer lie on a straight line through the origin, but on a straight line through the point $(3/16, 0)$. This illustrates that half-normal plots offer the potential to draw our attention to possible outliers in the data. In any case, Daniel (1959) showed that there may be more than one reason to study half-normal plots.

Figure 1: half-normal plotting as a way of detecting an outlier.

Lenth’s present article only deals with the best-known one, which is the detection of active effects.

Daniel (1976, Section 7.6) observed that some peculiarities of the data were not reflected in the half-normal plots. For this reason, he proposed to study signed effects without even using half-normal or normal plots. He also studies normal plots in the book, but only for signed residuals. In the book, no normal or half-normal plots of factor effects were made. Indeed, normal plotting only became fashionable due to the influential book by Box et al. (1978). Thus, the appropriate reference for normal instead of half-normal plotting of effects may well be Box et al. (1978), rather than the work of Daniel.

2.2 Some technical issues

Loh (1992) showed that the appearance of the points in normal plots can be entirely changed if the arbitrary – and + labels of the factor levels are swapped. For the example from Snee (1985), which involves five factors, 2^5 different normal effect plots can be created by swapping the labels of the levels of one or more factors. Some of the possible plots are much easier to judge by the eye than others. This problem is absent in half-normal plots. Wu and Hamada (2009) use the same kind of reasoning to prefer half-normal plots. Mee (2009) points out that one reason to prefer these plots might be the fact that the statistical significance of an effect is generally based on the size of its absolute value. Thus, we prefer half-normal plots over normal plots to judge effects from unreplicated experiments.

Of course, when using half-normal plots, there is the problem of subjectivity in drawing the line that marks the inactive effects. Lenth (1989) has written an immensely popular and useful paper on making a more objective evaluation of effects from unreplicated two-level experiments. The effects are evaluated using a pseudo-standard error based on the set of absolute values of the effects. It is calculated in three stages. First, the median of the full set of absolute-valued effects is multiplied with a consistency constant, so that an initial standard error estimate becomes available. Effects that are large with respect to this estimate are considered too big to provide information about the error variance. Therefore, in the second stage, these effects are removed from the set. Finally, the median of the remaining effects’ absolute values is multiplied by another consistency constant to result in the pseudo-standard error which we denote by PSE_{50} . The subscript 50 refers to the 50th percentile, which is the same as the median.

In a follow-up article, Haaland and O’Connell (1995) provide an overview of various alternatives to Lenth’s approach. One alternative to the PSE_{50} is the ASE (Dong, 1993), where the third stage for the pseudo-standard error calculation is based on the root mean square of the remaining effects. Another alternative is to use the PSE_{45} , meaning that the first stage is based on the 45th percentile of the absolute values of the effects. Haaland and O’Connell (1995) ended up recommending the ASE, PSE_{50} and PSE_{45} .

for practical use, where the choice depends on *a priori* expectations concerning the number of active effects. Schoen and Kaul (2000) provided extensive tables for consistency constants and critical values based on these pseudo-standard error approaches. In recent years, many other authors have published alternative approaches to analyze data from regular fractional factorial designs. We would welcome a review article discussing the pros and cons of the existing methods, possibly including a simulation study comparing the most attractive approaches.

The evaluation of effects both with a half-normal plot and with a robust standard error require that effect sparsity holds. For a half-normal plot, effect sparsity is required to identify a set of null effects pointing to the origin of the plot. For an evaluation with a robust error estimate, the effect sparsity is even more important, because the initial stage of constructing this estimate involves the median or the 45th percentile of the absolute values of the effects. If these effects are active, the initial error estimate is inflated. This inflation, in turn, might lead to an inflated final estimate. If the significance of effects is evaluated using an inflated estimate, the effects may erroneously be classified as inactive.

The Pareto plots that Lenth advocates instead of the probability plots do not provide checks on effect sparsity. Much as we like these Pareto plots, we think that the half-normal plots should be provided as well, both to check the sparsity assumption and to identify possible outliers in the data and inadvertent split-plotting. We believe that half-normal plots may still work well when less than 50% of the effects are inactive, provided there is a sufficient number of effects in total in the plots. The Pareto plot approach involving PSEs, however, should be adapted to continue to work if the effect sparsity condition is violated. In that case, the PSE should be based on a smaller quantile than the one used by default.

Additional conditions that need to be fulfilled for a valid evaluation with a half-normal plot as well as with a robust standard error estimate are that the estimates of the factor effects should be independent and normally distributed and that they should possess the same standard errors. Many scenarios exist in which at least one of these conditions does not hold. One such scenario is when a split-plot design, a strip-plot design or another design with restricted randomization is used, either inadvertently or intentionally.

2.3 Restricted randomization

Many industrial experiments are not completely randomized. This may be due to the presence of hard-to-change factors or due to the fact that the experiments span multiple steps of a process; see Goos and Jones (2011, Section 10.3.4) for a discussion of the different disguises of a split-plot design. Depending on the exact two-level design utilized, half-normal plotting or evaluation with a robust standard error may or may not work well.

For a regular split-plot design, half-normal plotting or evaluation with a PSE may work if all effects are either estimated in the whole-plot stratum or in the subplot stratum. In that case, there are two sets of effect estimates: one with a larger standard error and one with a smaller standard error. For each set of effects, a different half-normal plot (Bisgaard, 2000) or a different PSE is required. The main problem is that, oftentimes, one of these sets contains only a limited number of effects. For that set of effects, a PSE-based test will not be powerful and half-normal plots will not permit separation of active and inactive effects. Schoen (1999) states that at least seven effect estimates should appear in a half-normal plot for it to be useful.

For a regular strip-plot design, half-normal plotting or evaluation with a PSE may work if all effects are either estimated in the row stratum, the column stratum or the run stratum. In that case, there are three sets of effect estimates, one for each of these strata. Again, for each set of effects, a different half-normal plot or PSE is required. Here too, the main problem is that, generally, at least one of these sets contains only a limited number of effects, which renders half-normal plotting or PSE-based evaluation of the corresponding effects problematic.

By revisiting a regular strip-plot example of Vivacqua and Bisgaard (2004), Arnouts et al. (2010) demonstrate that a generalized least squares analysis may result in the detection of a larger number of active effects

than an analysis relying on normal plots. This example is one where there are very few effects in the column stratum.

In case the split-plot, strip-plot or related design is based on a nonregular fractional factorial design or an optimal design, half-normal plots or PSE-based evaluations become virtually useless. To a large extent, this is also true for completely randomized nonregular fractional factorial designs.

3 Nonregular and optimal designs

The best-known examples of nonregular fractional factorial designs are Plackett-Burman (PB) designs. Plackett-Burman designs as well as other nonregular designs are increasingly utilized for experimentation. There are two main reasons for this. First, nonregular designs offer more flexibility in terms of run size, as they exist whenever the number of runs is a multiple of four, whereas regular fractional factorial designs only exist when the number of runs is a power of two. Second, it is now recognized that nonregular designs allow a more diverse set of regression models to be estimated than regular fractional factorial designs. A disadvantage is the fact that the analysis of these designs is more complicated (i.e., a careful linear regression analysis is required), so that, in our consulting experience, certain experimenters feel more comfortable using regular fractional factorial designs. Also, the estimable effects in a regular design have the minimum possible standard error. We therefore think that both regular and nonregular designs have merit, but we would like to point out that the advantages of using nonregular designs, in our view, outweigh the disadvantage of a more complicated analysis. We would rather be able to estimate more interaction effects (with a nonregular design) than fewer interaction effects (with a regular design). The complete aliasing of interactions in regular fractional factorial designs will often necessitate follow-up experiments to disentangle aliased effects, while this will often not be the case for nonregular designs.

3.1 Complete randomization

When using nonregular fractional factorial designs, the estimates of the main effects and the estimable two-factor interactions often do not have the same standard errors, even when the design is completely randomized. Also, the estimates are generally not all independent. This is due to the fact that the two-factor interaction effects are often partially aliased with the main effects and/or with other two-factor interaction effects. Consequently, the significance of the main effect estimates and the two-factor interaction effect estimates cannot be evaluated in a half-normal probability plot. For the same reason, the PSE approach of Lenth cannot be used.

One special case where half-normal plots and PSE-based evaluation may remain useful is in the analysis of data from resolution-IV nonregular designs where the main effects are independent of the two-factor interactions. The main effects can then be evaluated with half-normal plots or using PSEs, while interactions can be explored using regression techniques (Miller and Sitter, 2001).

Increasingly so, optimal experimental designs are considered as alternatives to traditional regular fractional factorial designs, due to the presence of constraints on the factor levels (i.e., due to the fact that certain combinations of factor levels are disallowed) or due to budget constraints. Both types of constraints often cause the experimental design to be non-orthogonal, as a result of which the estimates of the main effects and the two-factor interactions are dependent and do not have the same standard errors. In those cases, a half-normal plot and Lenth's approach are again not appropriate.

3.2 Restricted randomization

The combination of nonregular or optimal experimental designs, on the one hand, and restricted randomization, on the other hand, does not have a positive impact on the usefulness of half-normal plots and Lenth's PSE. Frequently, factor effects are estimated using information from more than one stratum in a split-plot design, a strip-plot design or a related design. This causes the factor effects to have different variances

and results in a violation of an important condition for half-normal plots and pseudo-standard errors to be applicable.

4 Conclusion

Half-normal plots have proven to be very useful in an era where no fast computers were available to set up experiments and to analyze the resulting data. The lack of computing power has for a long time stimulated researchers to pay attention to ease of computation when proposing design of experiments methodology and methods of analysis. Unavoidably, this has led experimenters to simplify their problem so that it matched the available experimental designs and the available methods of analysis. This approach led to many successful applications of full factorial and regular fractional factorial two-level designs. The approach was successful in the sense that it led to good solutions for a simplified problem.

In the past two decades, things have changed dramatically because it has become possible to analyze more complicated data sets properly by means of powerful statistical software and computers. It has also become possible to create tailor-made experimental designs for virtually any practical problem. In other words, there is no need any more to simplify the problem at hand to fit a given design and analysis method. We view half-normal probability plot and PSE-based significance testing as useful for a specific type of experimental designs, i.e., full factorial and fractional factorial regular designs. In many practical scenarios, however, these designs cannot be used or can be improved upon.

In this contribution, we mentioned that the data analysis for nonregular designs is more complicated than that for regular designs. In doing so, we do not intend to do say that one needs a degree in statistics to analyze the data from nonregular designs. All that is required to get most of the salient insights out of a data set is a sound knowledge of linear regression analysis, including concepts such as stepwise regression, some goodness-of-fit diagnostics and multicollinearity. Nowadays, plenty of user-friendly software is available to perform linear regression analyses for any experimental design available.

Of course, it will always remain difficult to identify the best model from small experiments with numerous potential effects, independent of the design used. Therefore, we welcome more research on the analysis of data from nonregular two-level designs, in the spirit of Wolters and Bingham (2011) and Mee (2013), and to the implementations of these methods in user-friendly software. This will enable experimenters to combine the best designs available with the best methods of analysis available, so that their original problems rather than simplified ones can be solved in an optimal way.

References

- Arnouts, H., Goos, P., and Jones, B. (2010). Design and analysis of industrial strip-plot experiments. *Quality and Reliability Engineering International*, 26:127–136.
- Bisgaard, S. (2000). The design and analysis of $2^{k-p} \times 2^{q-r}$ split plot experiments. *Journal of Quality Technology*, 32:39–56.
- Box, G. E. P., Hunter, W. G., and Hunter, J. S. (1978). *Statistics for experimenters*. New York: Wiley.
- Daniel, C. (1959). Use of half-normal plots in interpreting factorial two-level experiments. *Technometrics*, 1:311–341.
- Daniel, C. (1976). *Applications of statistics to industrial experimentation*. New York: Wiley.
- Dong, F. (1993). On the identification of active contrasts in unreplicated fractional factorials. *Statistica Sinica*, 3:209–217.
- Goos, P. and Jones, B. (2011). *Optimal Design of Experiments: A Case Study Approach*. New York:Wiley.

- Haaland, P. D. and O’Connell, M. A. (1995). Inference for contrast-saturated fractional factorials. *Technometrics*, 37:82–93.
- Lenth, R. V. (1989). Quick and esy analysis of unreplicated factorials. *Technometrics*, 31:469–473.
- Loh, W. Y. (1992). Identification of contrasts in unreplicated factporial experiments. *Computational Statistics and Data Analysis*, 14:135–148.
- Mee, R. W. (2009). *A comprehensive guide to factorial two-level experimentation*. Springer-Verlag, New York, NY, USA.
- Mee, R. W. (2013). Tips for analyzing nonregular fractional factorial experiments,. *Journal of Quality Technology*, 45:330–349.
- Miller, A. and Sitter, R. R. (2001). Using the folded-over 12-run Plackett-Burman design to consider interactions. *Technometrics*, 43:44–55.
- Schoen, E. D. (1999). Designing fractional two-level experiments with nested error structures. *Journal of Applied Statistics*, 26:495–508.
- Schoen, E. D. and Kaul, E. A. A. (2000). Three robust scale estimators to judge unreplicated experiments. *Journal of Quality Technology*, 32:276–283.
- Snee, R. D. (1985). Experimenting with a large number of variables. In: R.D. Snee, L.B. Hare, and J.B. Trout (eds),. *Experiments in industry: design, analysis and interpretation of results*. Quality Press, Milwaukee.
- Vivacqua, C. and Bisgaard, S. (2004). Strip-block experiments for process improvement and robustness. *Quality Engineering*, 16:495–500.
- Wolters, M. A. and Bingham, D. R. (2011). Simulated annealing model search for subset selection in screening experiments. *Technometrics*, 53:225–237.
- Wu, C. F. J. and Hamada, M. S. (2009). *Experiments: Planning, Analysis, and Parameter Design Optimization*. 2nd edition, Wiley, New York, NY, USA.